


Marshall A1

Ireland (1007-1026 ft)

- Minor separation between density porosity and BVW
- High GR (+100 API) due to micaceous sand (georeport)
- Some gas show (bubbles) observed (georeport)
- $Sw + 90\%$
- **Wet Sand**



Marshall A-1

