



TRIOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED
MAR 19 2012

Test Ticket

NO. 46270

4/10

BY: _____

Well Name & No. Ring #1 Test No. 4 Date 3-16-12
 Company Double D's LLC Elevation 2087 KB 2079 GL
 Address 133 E. 12th Hays, Ks 67601-3607
 Co. Rep / Geo. AL Downing Rig Discovery 193
 Location: Sec. 12 Twp. 13^s Rge. 20^w Co. Ellis State Ks

Interval Tested 3710-3762 Zone Tested Arbuckle
 Anchor Length 52 Drill Pipe Run 3675 Mud Wt. 9
 Top Packer Depth 3705 Drill Collars Run 30 Vis 52
 Bottom Packer Depth 3710 Wt. Pipe Run - WL 8.8
 Total Depth 3762 Chlorides 4000 ppm System LCM 1 1/2 #

Blow Description IFP - WEAK TO STRONG IN 7 MIN
ISIP - 1/4" BLOW BACK
FFP - WEAK TO STRONG IN 9 MIN
FSTIP - SURFACE BLOW

Sec	Feet of	%gas	%oil	%water	%mud
<u>156</u>	<u>GIP</u>				
<u>575</u>	<u>CO</u>				
<u>145</u>	<u>MGO</u>	<u>25</u>	<u>55</u>	<u>20</u>	

Sec Total 720 BHT 119 Gravity 27 API RW - @ - °F Chlorides - ppm
 Test 1125
 Jars _____
 Safety Joint _____
 Circ Sub _____
 Hourly Standby _____
 Mileage 32 RT 44.80
 Sampler _____
 Straddle _____
 Shale Packer _____
 Extra Packer _____
 Extra Recorder _____
 Day Standby _____
 Accessibility _____
 Sub Total 1169.80

T-On Location 0740
 T-Started 0840
 T-Open 1030
 T-Pulled 1330
 T-Out 1558

Initial Open 30
 Initial Shut-In 45
 Initial Flow 45
 Initial Shut-In 60

Comments _____
 Ruined Shale Packer _____
 Ruined Packer _____
 Extra Copies _____
 Sub Total 0
 Total 1169.80
 MP/DST Disc't _____

Approved By _____ Our Representative RAY SCHWAGER *Thank you*
 Triobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.