



# TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED  
MAY 03 2012

## Test Ticket

NO. 47719

Well Name & No. Reichert #1 Test No. 1 Date 4/28/12  
 Company Double D's LLC Elevation 1988 KB 1981 GL  
 Address 133 E 127th Hays KS 67601  
 Co. Rep / Geo. Al Downing Rig Discovery #3  
 Location: Sec. 23 Twp. 15 Rge. 19 Co. L11.5 State KS

Interval Tested 3290-3317 Zone Tested KC" C"  
 Anchor Length 27 Drill Pipe Run ~~\_\_\_\_\_~~ Mud Wt. 8.6  
 Top Packer Depth 3285 Drill Collars Run 30 Vis 45  
 Bottom Packer Depth 3290 Wt. Pipe Run \_\_\_\_\_ WL 8.0  
 Total Depth 3317 Chlorides 4,500 ppm System LCM 145

Blow Description IF - BOB in 2 1/2 min  
ISF - No blow  
FF - BOB in 4 min  
FSI - No blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>1</u>	<u>oil</u>				
<u>769</u>	<u>water</u>				
_____	_____				
_____	_____				
_____	_____				

Rec Total 770 BHT 108 Gravity \_\_\_\_\_ API RW .07 @ 65 °F Chlorides 130,000 ppm  
 (A) Initial Hydrostatic 609  Test 1150 T-On Location 18:20  
 (B) First Initial Flow 62  Jars \_\_\_\_\_ T-Started 19:15  
 (C) First Final Flow 210  Safety Joint \_\_\_\_\_ T-Open 21:20  
 (D) Initial Shut-In 613  Circ Sub \_\_\_\_\_ T-Pulled 23:55  
 (E) Second Initial Flow 225  Hourly Standby \_\_\_\_\_ T-Out 1:45  
 (F) Second Final Flow 386  Mileage 16 x 2 49.60 Comments \_\_\_\_\_  
 (G) Final Shut-In 600  Sampler \_\_\_\_\_  
 (H) Final Hydrostatic 4559  Straddle \_\_\_\_\_  Ruined Shale Packer \_\_\_\_\_  
 Shale Packer \_\_\_\_\_  Ruined Packer \_\_\_\_\_  
 Extra Packer \_\_\_\_\_  Extra Copies \_\_\_\_\_  
 Extra Recorder \_\_\_\_\_ Sub Total 0  
 Day Standby \_\_\_\_\_ Total 1199.60  
 Accessibility \_\_\_\_\_ MP/DST Disc't \_\_\_\_\_  
 Sub Total 1199.60

Approved By \_\_\_\_\_ Our Representative Butch D...

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.