

Lease: Rous #1-28

SEC: 28 TWN: 16S RNG: 11W

County: BARTON State: Kansas

Drilling Contractor: L. D. Drilling, Inc -

Rig 1


Elevation: 1920 EGL Field Name: Kraft-Prusa

Pool: Infield Job Number: 116

DATE February 24 2018 DST #1 Formation: LKC K Test Interval: 3282 - Total Depth: 3310'

Time On: 08:45 02/24 Time Off: 14:50 02/24

Time On Bottom: 10:54 02/24 Time Off Bottom: 10:54 02/24





Lease: Rous #1-28

SEC: 28 TWN: 16S RNG: 11W

County: BARTON State: Kansas

Drilling Contractor: L. D. Drilling, Inc -

Recovery

Water

0%

Rig 1

Elevation: 1920 EGL Field Name: Kraft-Prusa

Pool: Infield Job Number: 116

DATE February 24 2018

DST #1 Formation: LKC K Test Interval: 3282 -

Total Depth: 3310'

3310'

Time On: 08:45 02/24

Time Off: 14:50 02/24

Time On Bottom: 10:54 02/24 Time Off Bottom: 10:54 02/24

교 0.005

Recovered

Description of Fluid <u>Foot</u> **BBLS** 0.01026 1 **SLOCM**

Gas % 0

<u>Oil %</u> Water % 0

Oil

1%

Mud % 99

Mud

99%

Total Recovered: 1 ft

Total Barrels Recovered: 0.01026

Reversed Out NO

		Recovery	at a glance
0.0	1 —		

Gas

0%

Initial Hydrostatic Pressure	1581	PSI
Initial Flow	10 to 12	PSI
Initial Closed in Pressure	28	PSI
Final Flow Pressure	12 to 13	PSI
Final Closed in Pressure	19	PSI
Final Hydrostatic Pressure	1569	PSI
Temperature	96	°F
Pressure Change Initial	33.9	%
Close / Final Close		



SEC: 28 TWN: 16S RNG: 11W

County: BARTON State: Kansas

Drilling Contractor: L. D. Drilling, Inc -

Rig 1

Elevation: 1920 EGL Field Name: Kraft-Prusa

Pool: Infield Job Number: 116

DATE February 24 2018

DST #1 Formation: LKC K Test Interval: 3282 -

Total Depth: 3310'

3310'

Time On: 08:45 02/24

Time Off: 14:50 02/24

Time On Bottom: 10:54 02/24 Time Off Bottom: 10:54 02/24

REMARKS:

10. WSB. Built to 1 3/4 inch

1C. NOBB

Equipment broke on second opening.

TOOL Sample. 1% O 99% M



SEC: 28 TWN: 16S RNG: 11W

County: BARTON State: Kansas

Drilling Contractor: L. D. Drilling, Inc -

Rig 1

Elevation: 1920 EGL Field Name: Kraft-Prusa

3287 FT

Pool: Infield Job Number: 116

DATE February 24 2018

DST #1 Formation: LKC K Test Interval: 3282 -Total Depth: 3310'

3310'

Bottom Recorder:

Time On: 08:45 02/24 Time Off: 14:50 02/24

Time On Bottom: 10:54 02/24 Time Off Bottom: 10:54 02/24

Down Hole Makeup

Heads Up: 29.32 FT Packer 1: 3277 FT

Drill Pipe: 3278.75 FT Packer 2: 3282 FT

ID-3 1/4 Top Recorder: 3266.42 FT

Weight Pipe: 0 FT

ID-2 7/8 Well Bore Size: 7 7/8

Collars: 1" **Surface Choke:** ID-2 1/4

Test Tool: 33.57 FT **Bottom Choke:** 5/8"

ID-3 1/2-FH

Jars

Safety Joint

Total Anchor: 28

Anchor Makeup

1 FT

0 FT

Packer Sub:

Perforations: (top): 3 FT

4 1/2-FH

Change Over: 0 FT

Drill Pipe: (in anchor): 0 FT

ID-3 1/4

Change Over: 0 FT

Perforations: (below): 24 FT

4 1/2-FH



Lease: Rous #1-28

SEC: 28 TWN: 16S RNG: 11W

County: BARTON State: Kansas

Drilling Contractor: L. D. Drilling, Inc -

Rig 1

Elevation: 1920 EGL Field Name: Kraft-Prusa

Pool: Infield Job Number: 116

DATE February 24 2018 DST #1 Formation: LKC K

Test Interval: 3282 -

Total Depth: 3310'

3310'

Time On: 08:45 02/24 Time Off: 14:50 02/24

Time On Bottom: 10:54 02/24 Time Off Bottom: 10:54 02/24

Mud Properties

Mud Type: Chem Weight: 9.3 Viscosity: 51 Filtrate: 10.4 Chlorides: 6300 ppm



Lease: Rous #1-28

SEC: 28 TWN: 16S RNG: 11W

County: BARTON State: Kansas

Drilling Contractor: L. D. Drilling, Inc -

Rig 1

Elevation: 1920 EGL Field Name: Kraft-Prusa

Pool: Infield Job Number: 116

DATE February 24 2018 DST #1 Formation: LKC K

Test Interval: 3282 -

Total Depth: 3310'

3310'

Time On Bottom: 10:54 02/24 Time Off Bottom: 10:54 02/24

Gas Volume Report

1st Open 2nd Open

Time Orifice PSI MCF/D	Time	Orifice	PSI	MCF/D
------------------------	------	---------	-----	-------